

図 1




図 2




図 3

PC材
 $B_m=0.2T$
 $f=8Hz$




図 4

PC材
 $B_m=0.2T$
 $f=8Hz$





図 5



5/7

図 6

PC材
 $B_m=0.65T$
 $f=50Hz$




図 7

PC材
 $B_m=0.65T$
 $f=50Hz$




図 8

PB材
 $B_m=0.9T$
 $f=50Hz$




図 9

PD材
 $B_m=0.9T$
 $f=50Hz$




図 10

